





49' (14.94m) 1999 Eastbay Mount Pleasant South Carolina United States



OVERVIEW

Manufacturer: Eastbay

Engines: Hull Material: Fiberglass
Engine Model: Cruise Speed: Knots
Engine HP: Max Speed: Knots
Beam: 16' 0" Cabins/Heads: /

Max Draft: 4' 4" Fuel Type: Diesel

Water: 176 G (666.23 L) Fuel: 775 G (2933.69 L)





Peter Dodds peter.dodds@charlestonyachtsales.com

1-843-343-4398



Data Sheet

Category: Downeast Subcategory: Motor Yachts

Condition: Used Model Year: 1999 Refit Year: 2021

Beam: 16' Max Draft: 4' 4" LOA: 49'

(14.94m) LOD: 52' Knots Knots

Fuel Type: Diesel

Hull Material: Fiberglass

Fuel Tank: 775 gal (2933.69 liters) Fresh Water: 176 gal (666.23 liters)

Imported: No

HIN/IMO: GNDN0007D999

Engines/Generators



Summary/Description

CANVASBACK is an exceptional example of this popular Grand Banks Model. Her condition reflects the pride of ownership exhibited by her knowledgeable owner who has spared no cost in keeping her maintained and updated to the highest standard. From her recent Pearl Grey Awlgrip to her new Garmin GPS, recent Caterpillar service and new canvas she is very much up to date. A full list of her upgrades are contained below. Anyone considering this type of vessel would be remiss in not inspecting CANVASBACK, she is turnkey and ready for new adventures. 2021 Upgrades: New CAT service interval including engine oil and gear oil samples Genset service and oil samples New Pearl Grey Awlgrip topsides and Faux teak transom New cockpit enclosure Newly upholstered Pompanette Helm Chair and companion chair Newly upholstered cockpit settee New Raritan icemaker in pilothouse New ceiling in pilothouse New interior headliner Service both Vacu Flush toilets New CAT Data large color screen engine data Service four AC units New Fridge and freezer 2022 Factory refurbish steering ram Factory rebuilt 5 Lewmar hatches New exterior cushions and pilothouse cushions New mesh deadlight and hatch covers Flush and cleaned water tanks Flush and clean fuel tanks Replaced all batteries. All new exterior varnish



