



Aurora

28' (8.53m) 1985 Tartan 28
Houston Texas United States



OVERVIEW

\$20,000

Manufacturer:	Tartan		
Engines:		Hull Material:	Fiberglass
Engine Model:		Cruise Speed:	
Engine HP:		Max Speed:	
Beam:	9' 10"	Cabins/Heads:	1 / 1
Max Draft:	4' 11"	Fuel Type:	Diesel
Water:		Fuel:	



Data Sheet

Category: Cruiser-Racer

Condition: Used

Model Year: 1985

Beam: 9'10" (3.00m)

Max Draft: 4' 11" (1.50m)

LOA: 28' 3" (8.61m)

LWL: 23' 8" (7.21m)

Cabins: 1

Sleeps: 5

Single Berths: 3

Double Berths: 1

Heads: 1

Fuel Type: Diesel

Hull Material: Fiberglass

Displacement: 7450 HIN/IMO:

TAR28048J485

Engines/Generators

Summary/Description

The Tartan 28 is sloop rigged with a fin keel, keel stepped mast and a spade rudder. With a Yanmar diesel, accommodations for 5 a head and galley Aurora will make a great inexpensive weekender. Vee berth forward with head just aft to starboard, followed by salon with galley aft to port and quarter

The Tartan 28 is sloop rigged with a fin keel, keel stepped mast and a spade rudder. With a Yanmar diesel, accommodations for 5 a head and galley Aurora will make a great inexpensive weekender.

Vee berth forward with head just aft to starboard, followed by salon with galley aft to port and quarter berth aft of starboard nav station.

2022

☐ Bottom scraped

☐ Complete wax

2021

☐ Two new battery chargers

☐ New main sail cover

☐ New boom tent

2020

☐ Solar vent

☐ Two new deep cycle marine house batteries

☐ Two new bilge pumps

2019

☐ New bottom paint- 2 coats of black Ultrakote- NO BLISTERS FOUND

☐ Hull compounded and waxed

☐ All thru-hulls serviced

☐ Standing rigging inspected

☐ New prop installed

☐ New jib sheets

☐ New main sheet

☐ New main halyard

☐ New stainless steel lifelines

☐ Replaced all light fixtures and installed LED bulbs

- New throttle cable
- New engine water pump
- All portlights and screens replaced

Asking price accounts for: Starboard side toerail damaged during hurricane prior to ownership. Leakage and damage to some of the interior wood on starboard side. No longer leaking.





















































