



MONACO

125' (38.10m) 1982 Feadship
Barcelona Spain



OVERVIEW

Manufacturer: *Feadship*

Engines: 2 Caterpillar

Engine Model: D348

Engine HP: 920

Beam: 23' 10"

Max Draft: 10' 3"

Water: 1849 G (6999.22 L)

Hull Material: Steel

Cruise Speed: 11 Knots

Max Speed: 15 Knots

Cabins/Heads: 4 / 6

Fuel Type: Diesel

Fuel: 7396 G (27996.89 L)

€5,600,000



Data Sheet

Category: Motor Yachts
Condition: Used
Model Year: 1982
Beam: 23'10" (7.26m)
Max Draft: 10' 3" (3.12m)
Min Draft: 9' 10" (3.00m)
LOA: 125' (38.10m)
Cabins: 4
Heads: 6

Maximum Speed: 15 Knots
Cruise Speed: 11 Knots
Fuel Type: Diesel
Hull Material: Steel

Fuel Tank: 7396 gal (27996.89 liters)
Fresh Water: 1849 gal (6999.22 liters)
Stock #: B92137

Engines/Generators

Engine 1

Caterpillar
D348
Inboard
920HP
686.04KW
Fuel: Diesel
Hours: 7242

Engine 2

Caterpillar
D348
Inboard
920HP
686.04KW
Fuel: Diesel
Hours: 7235

Summary/Description

MONACO was built by Royal Van Lent in 1981 and delivered to her first owner in 1982. The exterior and technical designs are by naval architect de Voogt and the interior design is by Terence Disdale.

MONACO was built by Royal Van Lent in 1981 and delivered to her first owner in 1982. The exterior and technical designs are by naval architect de Voogt and the interior design is by Terence Disdale. MONACO is beautifully maintained. She has classic Feadship pedigree. Her 40-year Lloyds survey and major refit in 2022/23 were done at the MB92 Super Yacht shipyard in Barcelona.

The details can be found in the listing and also regarding previous refits. More details on request

Mechanical Equipment

- (2) Caterpillar D348 Diesel 900 HP, 7242/7235 hours each as of Jan 2023 (since complete rebuild)
- Reintjes gearbox
- Shaft propulsion
- (2) fixed pitch propellers
- 35 degrees rudder angle
- Hydraulic C-Plath steering system
- Vosper MKII Type 4 (Underway only) stabilizers
- Vosper/Naiad Dynamics Model 20 (VT60) 55 kW Bow thruster
- (2) Zenoro John Deere 80 kW generators (New 2016), 8652/8596 hours each as of Jan 2023
- 400V and 220V electricity
- Shore power
- Lead Acid batteries
- Electric starter, main engine
- Lead-acid service
- Electric starter, generator
- Mastervolt chargers
- Eekels TBI shore power converter (New 2016)
- Emergency Batteries
- Hydraulic Steering, stabilizers, and cranes
- AirMarine air conditioning System throughout
- Water maker, 450 liters/hour
- Vacuum Jet toilet system
- Hamann sewage system
- Alfa Laval fuel centrifuge
- Racor filters

Navigation Equipment

- C-Plath magnetic compass
- Furuno SC-702 satellite compss

- Simrad AP 50 autopilot
- Furuno FCV 650 Echo sounder
- (2) Furuno radar, 9GHz X-Band
- AIS Furuno FA 170
- DGPS Furuno GP 170
- GPS Furuno GP 39
- Warstila/Transas NaviSailor 4000 ECS, chart plotter
- Furuno NX-300, Navtex
- Raymarine wind instruments
- Searchlights
- Cameras- (5) Samsung, fixed color cameras with (2) monitoring stations

Communication Equipment

- Sailor Fleet FBB 500, SATCOM
- VHF Icom M323/ M423GE
- SSB Sea 235
- Telephone exchange

Deck Equipment

- (2) Anchor windlasses, Foredeck capstans with gypsies
- (2) Aft warping capstans
- (2) 200 kg Galvanized steel anchors
- (2) Galvanized steel anchor chains (approx. 150m each)
- (2) Custom boat cranes (Pendennis) with 800 kg SWL
- Custom Fibreglass 2-piece passerelle with stainless steel handrails and teak inlays
- Marquipt side boarding ladder with varnished handrails
- Swim platform with swim ladder and handrails
- Awnings for bridge deck dining
- Covers for all exterior seats

Entertainment Equipment

- 40" flat screen + Surround sound system- Main Salon
- Surround sound system- Dining
- Flat-screen TV- Crew
- Fusion Speakers/Bluetooth Capable system- exterior

Galley and Laundry Equipment

- Zanussi cooktop and built-in ovens
- Additional bench-top oven
- Vacuum machine
- Deep fryer

- (2) Miele washing machines, (2) Miele dryers

Security and Safety Equipment

- SAFETY All LSA in accordance with Lloyds and Barbados requirements
- All fire equipment in accordance with Lloyds and Barbados requirements

Tender and Watersport Equipment

- (2) Novurania 550DL RIB tenders with Yamaha Four Stroke 115 hp outboards
- Laser Pico sailing dinghy
- (3) Water skis
- Towable wakeboard
- (2) Inflatable SUP boards
- Jobe Kick Flip inflatable towable toy
- Jobe inflatable 4-person Chaser
- Inflatable donut
- (8) Full sets of diving equipment

Refit and Maintenance Notes

WINTER 2022 / 2023

- Caterpillar Main Engine works- removed and serviced all intercoolers and heat exchangers, port engine head off and inspected with a replacement valve and head gasket, replacement of both turbos for each engine
- Full service of Zenoro generators- replacement of raw water pump on one generator
- Stabiliser system works- rebuilt hydraulic cylinders/rams, new accumulator, cooling and hydraulic pump overhaul, and visit by Naiad for system testing
- (New) wing station pneumatic for Main Engine controls pipework installed. Full system flush and install of oil filters.
- Main Fire, Bilge, and FW pumps onboard serviced and overhauled as per manufacture requirements
- Extensive exterior paint repairs and refinishing as required
- Entire exterior hull paint cleaned, machine polished and sealing by RMP Marine (A-Glaze)
- Lazarette Bilge and all exterior lockers- had full new paint system applied
- Removal and replacement of some teak planks/margins around yacht
- (New) exterior caulking as required for teak and paint works around yacht
- Foredeck and swim platform teak sanded
- Exterior varnish work- being stripped where needed and built up as required (New) caulking once varnish work is complete
- Tender works- sponson refresh of top sides including (New) grab handles and the rubber fender trims for sponsons replaced all around
- Tender outboards- replace some componentry by Yamaha, full service, and repaint of cowling covers and trims
- (New) Raymarine Anemometer and Speed Log installed
- (New) Nav computer upgrade for Warstila/Transas NaviSailor4000 ECS including (New) NMEA distribution splitter
- (New) Icom VHF DSC unit installed in wheelhouse
- (New) Grill/Salamander installed in Galley

- Interior touch-ups and repairs- including some leather ceiling panels, varnish, and wooden surfaces around the yacht

WINTER 2021/2022

- MB92 Barcelona for 40-year Lloyd's Register (LR) survey and comprehensive maintenance work.
- Hull thickness test carried out to satisfy LR requirements
- Megger Test equipment as per LR requirements
- Rudder and shaft clearances taken as per LR requirements
- Full service of steering systems of yacht as per LR
- Full repair and replacement of all anti-foul system onboard
- All (New) anodes installed including bow thruster and rudders
- Fuel and Oil tanks as per LR requirements- inspect, clean, repair, and paint as needed
- Fresh Water tanks as per LR requirements- inspect, clean, repair, and paint as needed
- All overboard valves serviced, and pressure tested as per LR requirements
- (New) Oily Water Separator system installed as per LR requirements
- Hamann system full service and rebuild of pumps and inspection of Grey/Black tanks including full clean, repair, and new paint system applied
- Service and updates made to water softener system onboard
- Service and overhaul of main Fridge/Freezer system in laundry
- Zenoro Generators servicing carried out at 7500hrs
- Caterpillar Main Engines- light service and inspection as required

WINTER 2020

- Repaint of Engine Room
- Exterior varnish and paint repairs and refinishing as required

WINTER 2016/2017 Refit in Pendennis Shipyard, UK

- (New) Zenoro John Deere 80 kW each generators installed with sound boxes
- (New) Electrical distribution panels in E.R. upgraded and (New) power management system
- All exterior varnish stripped and built up on exterior of yacht
- Full exterior paint of yacht including all hardware removed during process
- Main Caterpillar Engines - full rebuild back to zero hours (Dec 2016/Jan 2017)
- All teak decks sanded
- Haul-out for anti-fouling and full new system applied
- All tanks cleaned, painted, and small repairs made (per Lloyds standards)
- (New) AC system (overhaul and renewal of AC plant & chillers)
- (New) Air handlers around yacht
- Galley rebuilt / modernized including (New) cooktopoven
- Pipework replaced in E/R
- Upgrade/Overhaul steering system including Emergency Steering
- Hanamm System overhaul/Service
- All crew areas had full refurbishment
- (New) main deck aft sliding glass windbreaks
- (New) 2 x removable tender chocks
- 2 x Tender cranes fully overhauled and certified
- Laundry upgrades including (New) Miele dryers
- Fridge/Freezer overhaul and service
- (New) Carpet Main Saloon and Dining Room

- (New) Servowatch tank monitor systems installed
- (New) Samsung CCTV surveillance installed with 5 x cameras and monitors in wheelhouse and crew mess
- (New) AV setup in main salon and dining room
- Rebuild of main air compressor system onboard

WINTER 2013/2014

- MB 92 for 30 year Lloyd's survey and comprehensive maintenance work in E.R.
- 4G internet PepWave aerial and router fitted and connected to the yachts network
- Various varnish works - exterior and interior
- Various exterior paint works
- (New) carpet throughout interior except main salon/dining room
- Repaint of Hull, superstructure, and top sides by Rolling Stock
- Main Caterpillar Engines - full rebuild back to zero hours and service @11,500hrs)
- Bar area upgraded with more varnished teak and replaced Corian
- Teak deck full replacement and sanding of all decks
- Both generators overhauled and serviced to zero hours
- Haul-out for anti-fouling
- All tanks cleaned, small repairs, and painted (as per Lloyds Requirements)
- (New) KVH V7 Mini- V SAT installed
- (New) Furuno Satellite Compass installed
- (New) SeaTel 4004 TVRO Antenna and Sky TV installation
- (New) Sailor Fleet FBB 500 installed
- (New) New Speich windscreen wipers & electrical unit installed
- Master Cabin re-fit
- Bowthruster upgrade of Motor and Control Systems (Naiad Dynamics) in bridge and wing stations
- Replaced teak deck system all around yacht and sanded all as required
- (New) Mastervolt battery charger system installed
- (New) Bridge Furuno electronics and controls upgrade
- Anchor windlass system service

Disclaimer

The company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change or withdrawal without notice.





































