



Oriente

34' (10.36m) 2001 Sabre 34 Sedan
Beaufort North Carolina United States



OVERVIEW

Manufacturer:	Sabre	Hull Material:	Fiberglass
Engines:	2 Yanmar	Cruise Speed:	19 Knots
Engine Model:	6LP-STE	Max Speed:	24 Knots
Engine HP:	315	Cabins/Heads:	/
Beam:	12' 6"	Fuel Type:	Diesel
Max Draft:	3' 3"	Fuel:	250 G (946.35 L)
Water:	160 G (605.67 L)		

\$129,000



Data Sheet

Category: Downeast
Condition: Used
Model Year: 2001
Beam: 12'6" (3.81m)
Max Draft: 3' 3" (0.99m)
LOA: 34' (10.36m)

Maximum Speed: 24 Knots
Cruise Speed: 19 Knots
Fuel Type: Diesel
Hull Material: Fiberglass

Dry Weight: 17800 lbs
Fuel Tank: 250 gal (946.35 liters)
Fresh Water: 160 gal (605.67 liters)
HIN/IMO: HWSL4041H001

Engines/Generators

Engine 1

Yanmar
6LP-STE
Inboard
315HP
234.90KW
Fuel: Diesel
Hours: 1000
Year: 2001
Location: Port

Engine 2

Yanmar
6LP-STE
Inboard
315HP
234.90KW
Fuel: Diesel
Hours: 1000
Year: 2001
Location: Starboard

Generator 1

Onan
7.5MDKBJ-1101C
Hours: 130

Summary/Description

Quality construction and a beautiful teak interior characterized the Sabreline 34 when she was introduced in 1991. She's built on the same modified-V hull used in the production of the original Sabreline 36 with moderate beam and a shallow keel for directional stability. Like all Sabre boats (sail o

" ORIENTE " is a beautiful 1991 Sabre 34 Flybridge Sedan, Complete hull and top side paint 2021, only 1000 original hours on 315 HP Yanmars that are fully up to date complete with 1000 service. New generator in 2018 with 120 current hours. See " Full Specifications" for complete list of update's and improvements.

She is easy to see in Beaufort, North Carolina

Owners records since purchase late 2018

electronics New vhf radio Flybridge upgrade 2019

electronics New vhf radio Lower helm upgrade 2019

electronics New fusion speakers Salon upgrade 2019

electronics New media player Flybridge upgrade 2019

electronics New media player Lower helm upgrade 2019

electronics New mfd 7 inch Garmin upgrade 2019

electronics New mfd 9 inch Garmin upgrade 2019

electronics New mfd 9 inch Garmin upgrade 2021

electronics New depth sounder transponder Garmin in hull upgrade 2019

electronics New depth sounder transponder Through Hull Chirp upgrade 2021

engine New cooling system hoses Both engines Maintenance 2018

engine New belts Both engines Maintenance 2018

engine 100 hour service Generator Maintenance 2020

engine 1000 service Both engines Maintenance 2020

engine Replace port transmission Port engine Repair 2020

engine Alignment Both engines Repair 2020

engine Replace exhaust hose Both engines Repair 2023

engine Replace raw water pump Port engine Repair 2023

engine Oil replacement Both engines Maintenance 2023

engine Oil replacement Generator Maintenance 2023

engine Impeller replacement Maintenance 2023

engine New tach Starboard helm Repair 2018

engine Replaced PSSI shaft seals Both engines Repair 2020

engine New throttle and shifting cables Repair 2019

exterior Gel coat cracks repaired Repair 2021

exterior New AlexSeal paint Alex Seal topside, decks and hull Repair 2021

exterior New pvc trim Replaced teak with low maintenance trim upgrade 2023

exterior Sliding door gaskets replaced Repair 2021

exterior Window seals repaired Repair 2021

exterior New bench seat Flybridge upgrade 2019

exterior Standion leak repaired Repair 2019

exterior New helm seats Flybridge upgrade 2023

exterior New Bimini top Repair 2018

exterior Replaced sliding door lock Repair 2018

interior New salon blinds upgrade 2019

interior New salon cushions upgrade 2019

Sabre 34 Flybridge

1

interior New mattress Stateroom upgrade 2019

interior New toilet paper holder Head Repair 2019

interior new adjustable table upgrade 2020

interior New boarding door skin Repair 2019

interior Cabin sole refinished Repair 2023

interior New Stateroom fan upgrade 2023

systems Replace Bilge fan Repair 2021

systems New macinator Repair 2022

systems New waste hose Repair 2022

systems Replace fresh water pump Repair 2023

systems New waste vent hose Repair 2022

systems Tank tender hose and valve repair Repair 2020

systems Replaced aft bilge pump Repair 2021

systems New center bilge pump and through

hull

upgrade 2022

systems New Dry Bilge upgrade 2022

systems Rebuilt vacuflush head All interior components replaced and

new system pump

Maintenance 2020

systems New Fridge upgrade 2019

systems Replaced Aft Heating/cooling system Salon Repair 2019

systems New kitchen faucet upgrade 2020

systems New bath faucet upgrade 2020

systems New water heater Repair 2019

systems New LED navigation lights upgrade 2019

systems New fan in stateroom upgrade 2023

systems New anchor chain Repair 2021

systems USB outlets at at both helms upgrade 2019

Electronics

Lower HelmGarmin Color GPS Chartplotter / Depth Sounder

Robertson AP 11 Auto Pilot

ICOMVHF

Disclaimer

The company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change or withdrawal without notice.































