



35' (10.67m) 1978 Bristol 35.5 Centerboard
Indian Rocks Beach Florida United States



OVERVIEW

\$55,000

Manufacturer:	Bristol	Hull Material:	Fiberglass
Engines:		Cruise Speed:	
Engine Model:		Max Speed:	
Engine HP:		Cabins/Heads:	/
Beam:	10' 10"	Fuel Type:	Diesel
Max Draft:	5' 9"	Fuel:	
Water:			





Data Sheet

Category: Cruisers

Condition: Used

Model Year: 1978

Beam: 10'10" (3.30m)

Max Draft: 5' 9" (1.75m)

Min Draft: 3' 9" (1.14m)

LOA: 35' 6" (10.82m)

Fuel Type: Diesel

Hull Material: Fiberglass

Hull Shape: Monohull

HIN/IMO: BTY355200878

Engines/Generators



Summary/Description

This 1978 Bristol 35.5 is a wonderful example of a well-maintained and loved vessel. She has many notable upgrades. Her 39hp Yanmar diesel engine, installed in 2003, with approx. 1386 hours and all new canvas in 2021 are just a couple examples.

A Very Clean & Well-Maintained Shoal Draft/Centerboard Sloop!!

The Bristol 35.5 is a remarkable yacht. Her lines are stunning, her sailing performance exemplary, construction excellent, and interior spacious and attractive. Well-kept Bristol 35.5's have always been in demand and will continue to be.

This particular 1978 Bristol 35.5, "Talisman", is a wonderful example of a well-maintained and loved vessel. She has many notable upgrades. Her 39hp Yanmar diesel engine, installed in 2003, with approx. 1386 hours and all new canvas in 2021 are just a couple examples.

Most importantly, "Talisman" is a shoal draft model with a centerboard, providing a 3' 9" draft with the board up, which allows access to anchorages that would normally be unavailable to boats of this size.

This boat is ready to sail away! Call/Text/Email today to set up a showing!

Dimensions

Length Overall: 35.5ft

Max Bridge Clearance: 54ft

Min Draft: 3.75ft

Max Draft: 5.75ft

Beam: 10.83ft

Cabin Headroom: 6.25ft

Length at Waterline: 27.5ft



Tanks

Fresh Water Tank: 100 Gal

Fuel Tank: 30 Gal

Holding Tank: 30 Gal

Engine

Engine Make: Yanmar

Engine Model: 3JH3E

Engine Year: 2003

Total Power: 39hp

Engine Hours: 1386

Engine Type: Inboard

Fuel Type: Diesel

Galley

- 2-Burner Propane Stove
- S/S Sink
- Hot/Cold Water Pressure
- Ice Box
- Storage

Electronics

- Raymarine ST4000+ Autopilot
- Autohelm Wind-Depth-Speed
- Raytheon SL70 Radar
- Northstar 951X GPS Navigator
- Standard Horizon ECLIPSE+ VHF



- West Marine VHF75 Handheld
- Jensen MS2013BT Stereo w/ Bluetooth
- (2) Cockpit Speakers
- Richie 5.5" Compass

Mechanical / Electrical

- 2003 Yanmar 3JH3E 39hp Diesel Engine w/ approx. 1386 hours
- Mercury 6hp 4-Stroke Outboard Engine
- Heart Interface Link 2000 Inverter/Charger
- (2) House Batteries & (1) Engine Start Battery
- Pump Cycle Monitor for bilge pump
- Raritan Manuel Head
- Macerator Pump
- (2) Solar Fans
- Shore Power
- Water Heater
- 30-Gallon Fuel Tank
- 30-Gallon Holding Tank
- (2) 50-Gallon Freshwater Tanks, each

Sails / Rigging

- 110% Roller Furling Jib
- 130% Roller Furling Jib
- Furlex Roller Furler
- Quantum Mainsail
- Spinnaker w/ Sock
- Harken Hardware
- (2) Lewmar #44 Two-Speed, Self-Tailing Winches
- (5) Winch Handles

Deck / Hull / Cockpit

- Stainless Steel 35# CQR Anchor w/ 100' chain & 100' rode combo
- Lewmar Electric Winch
- Last Bottom Job in **2020**
- (2) S/S Dorades
- Screens for ports, hatches, & companionway
- **NEW** Canvas (Bimini, Dodger, Sail Cover, etc.) - **October 2021**
- Full Boat Canvas Cover (for winter storage)



- Cockpit Cushions
- Teak Cockpit Table
- Edson Steering Wheel w/ Lock

Safety

- Horseshoe Throwable
- (6) Standard Life Jackets
- (2) Self-Inflating PFD's
- (2) Fire Extinguishers
- (2) Dinghy Oars

Disclaimer

Preferred Yachts offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change, or withdrawal without notice.

Co-Brokerage Agreement

Preferred Yachts offers this listing on a 50-50 split with corresponding Florida licensed brokerages. Brokers unlicensed in Florida must contact listing broker to make arrangements that comply with Florida law.





























































