



38' (11.58m) 1984 Pearson 386
Rock Hall Maryland United States



OVERVIEW

Manufacturer:	<i>Pearson</i>		
Engines:	1 Westerbeke	Hull Material:	Fiberglass
Engine Model:		Cruise Speed:	6 Knots
Engine HP:	0	Max Speed:	7.3 Knots
Beam:	11' 6"	Cabins/Heads:	1 / 1
Max Draft:	5' 6"	Fuel Type:	Diesel
Water:	150 G (567.81 L)	Fuel:	45 G (170.34 L)

\$70,000



Data Sheet

Category: Sloop
Condition: Used
Model Year: 1984
Beam: 11'6" (3.51m)
Max Draft: 5' 6" (1.68m)
LOA: 38' 4" (11.68m)
LWL: 30' (9.14m)
Cabins: 1
V Berths: 1
Double Berths: 2
Heads: 1

Maximum Speed: 7.3 Knots
Cruise Speed: 6 Knots
Fuel Type: Diesel
Hull Material: Fiberglass
Hull Shape: Monohull
Hull Finish: White
Air Conditioning: Yes

Displacement: 16915 Bow Thruster: Yes
Fuel Tank: 45 gal (170.34 liters)
Fresh Water: 150 gal (567.81 liters)
Holding Tank: 20 gal (75.71 liters)
Imported: No
Designer: Bill Shaw
HIN/IMO: PEAXXXXXXXXX

Engines/Generators

Engine 1

Westerbeke
Inboard
Fuel: Diesel
Year: 1984

Summary/Description

If you are looking for a proven cruiser, that has been meticulously cared for AND under \$80,000... then step aboard Gypsy II. From the bottom to the sails, recent work shows pride of ownership- including the rigging and woodwork.

Upgrades and Major Maintenance

2008 & 2009

- Sea Canvas Boat Cover
- Professionally Replaced Topsides and Deck

2016

- Replaced Starter Motor
- Replaced A/C Water Pump

2017 & 2018

- New Mainsail (Quantum)
- New Jib (Quantum)
- Sea Talk Conversion Kit
- New Controller & Switch for Bow Thruster
- New Wiring for Bow Thruster
- All Exterior Teak Professionally Stripped & Refinished
- Replaced A/C Unit
- Replaced A/C Water Pump

2018 & 2019

- Replaced Sheaves
- Replaced Harken Furler (Jib)
- Replaced Standing Rigging
- Replaced Steaming/Deck Lights

2020

- Replaced Engine Lift Pump
- Replaced Toilet and Waste Hoses
- Replaced All Fuel Lines to the Engine

2021 & 2022

- Replaced All Exterior Canvas (Dodger, Bimini, and Connector)
- Hull Professionally Stripped
- New Barrier Paint on Hull
- New Bottom Paint
- Replaced NavPod in Cockpit
- Installed New Raymarine Axiom 12"

Disclaimer

The company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change or withdrawal without notice.















































