



Tide Up II

50' (15.24m) 2002 Hatteras 50 Convertible
Charleston South Carolina United States




OVERVIEW

Manufacturer: *Hatteras*

Engines:	2 Caterpillar	Hull Material:	Fiberglass
Engine Model:	3412 E	Cruise Speed:	
Engine HP:	1400	Max Speed:	
Beam:	16' 1"	Cabins/Heads:	3 / 2
Max Draft:	5' 4"	Fuel Type:	Diesel
Water:	184 G (696.52 L)	Fuel:	1160 G (4391.08 L)

\$625,000



Mike O'Connor moconnor@hmy.com

1-561-635-5968



Data Sheet

Category: Sport Fishing
Condition: Used
Model Year: 2002
Beam: 16'1" (4.90m)
Max Draft: 5' 4" (1.63m)
LOA: 50' (15.24m)
Cabins: 3
Heads: 2

Fuel Type: Diesel
Hull Material: Fiberglass

Fuel Tank: 1160 gal (4391.08 liters)
Fresh Water: 184 gal (696.52 liters)
Holding Tank: 85 gal (321.76 liters)
HIN/IMO: N/A

Engines/Generators

Engine 1

Caterpillar
3412 E
Inboard
1400HP
1043.98KW
Fuel: Diesel
Hours: 3100

Engine 2

Caterpillar
3412 E
Inboard
1400HP
1043.98KW
Fuel: Diesel
Hours: 3100



Summary/Description

Tide Up II is the nicest 50' Hatteras on the market, hands down. With continuous updates inside and out, meticulously maintained 3412 CAT engine reliability and new northern lights generator makes this boat is turnkey for any application.

Tide Up II is the nicest 50' Hatteras on the market, hands down. With continuous updates inside and out, meticulously maintained 3412 CAT engine reliability and new northern lights generator makes this boat is turnkey for any application. This 2002 50' Hatteras has had an exceptional line of ownership that have taken pride in her since she was splashed. The Hatteras 50' comes with years worth of documented service from reputable marine mechanics. It is easily shown in Charleston, South Carolina. Will not disappoint.

Highlights

2016

- VETUS bow thruster installed
- Bottom sandblaster/blistered filled/repaint

2017

- New main engine coolant pumps

2018

- New Garmin marine network including:
- Twin GPSMAP 6212's
- Open array radar
- Garmin sonar module/transducer
- Fusion XM radio/6 speakers
- All New AC condensing units
- New AC pump
- New bridge upholstery
- New carpet throughout

2019

- Remanufactured ice chipper installed
- New main engine aftercoolers installed
- Full Awlcraft 2000 paint job, hull and all topside areas. Old paint removed, primed, respray
- New Raritan marine elegance heads (2)
- New Underwater Lights/Lumitec (3)

2020

- New Northern Lights 16kw Genset (350 Hours)
- Garmin autopilot/smart pump
- New steering ram
- New bridge 3 sided enclosure (EZ2CY)
- New battery charger



- Repack rudder posts
- New SS convection microwave
- New SS salon icemaker
- New upholstery salon
- New KVH Tracvision/DirecTV receiver
- New trim tab pump
- New Cockpit Cover/Shade

2021

- New AGM 8D's (4)
- New exhaust risers
- New 240V Freshwater Pump
- Turbos Blueprinted
- New Main Engine Risers
- New stove top

2022/2023

- Replaced Turbo
- New A/C circulating pump
- New battery charger
- New additional batteries

Salon

- L-shaped couch aft to starboard w/ storage
- L-shaped forward settee to port
- Barrel ordinary swivel chair
- Overhead stereo speakers
- New Vizio flat panel TV
- New upholstery
- New Carpet
- Surround sound stereo system

Galley/Dinette

- Amtico Teak and holly flooring
- Ample storage & cabinetry
- Sink w/ SS water faucet
- Sub Zero under counter refrigerators (2) and freezers (2)
- New stainless steel ice maker
- New stainless steel convection microwave
- New stovetop
- Garbage disposal



Master Stateroom & Head

- Master island queen berth with storage underneath
- Drawer storage below berth
- Flat screen TV
- En suite head & shower with mirror and headliner

VIP Stateroom/Head

- VIP stateroom forward w/ over/under bunks
- Drawer storage below
- Storage and lockers to port
- En suite head & shower shared with guest cabin

Guest Stateroom

- Upper and lower bunked berths
- Drawer storage below
- Closet aft with hanging storage
- En suite head with private entrance- shared with VIP stateroom

Companionway

- Washer/dryer

Flybridge/Electronics

- Hard top with lighting
- Pancake teaser reels
- (2) Helm chairs
- JL Audio speakers
- Fusion XM radio
- Vetus bow thruster
- KVH Tracvision
- New upholstery
- New EZ2CY enclosure

New Garmin networking including

- Dual Garmin 6212's charts
- Open array radar
- Garmin sonar module
- Garmin auto pilot / smart pump
- 2 new Garmin VHF's



Cockpit/Hull

- Rocket launcher
- Transom door with gate
- Fusion stereo
- JL Audio stereo speakers
- Fish box
- Fresh water hook- up
- Tackle center & drawers to port
- Cockpit freezer & sink
- Tackle center to starboard
- Rupp triple spreader riggers
- Overhead lights
- New cockpit sun shade
- Access to engine room
- Glendinning Cable Master 50 Amp shore power
- Remanufactured ice chipper
- New Lumitec underwater lights
- FULL Awlcraft 2000 paint job

Engine Room/Mechanical

- Twin CAT 3412 E 1400 hp engines - 3050 hours
- New Northern lights generator (2020) - 350 hours
- Dripless shaft seals
- All new A/C condensing units/ new A/C pump
- New main engine coolant pumps
- New aftercoolers
- Fuel and oil transfer system
- Fixed Fire Halon system
- New rudder post
- New trim tab pump
- New 240v Freshwater pump
- New main engine risers
- Turbos blueprinted

Mechanical Disclaimer

Engine and generator hours are as of the date of the original listing and are a representation of what the listing broker is told by the owner and/or actual reading of the engine hour meters. The broker cannot guarantee the true hours. It is the responsibility of the purchaser and/or his agent to verify engine hours, warranties implied or otherwise and major overhauls as well as all other representations noted on the listing brochure.

Disclaimer

The company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate



such details as the buyer desires validated. This vessel is offered subject to prior sale, price change or withdrawal without notice.



Hatteras 50 Tide Up II - Profile 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Profile 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Profile 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Aerial Profile 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Aerial Profile 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Flybridge 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Flybridge 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Flybridge 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Flybridge 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Salon 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Salon 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Salon 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Dinette 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Galley 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Galley 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Stairway 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Master Stateroom 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Master Stateroom 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Master Head 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Master Head 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - VIP Stateroom 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - VIP Stateroom 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Aerial Profile 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Engine Room 2002 Hatteras 50 Convertible - Tide Up II



Hatteras 50 Tide Up II - Engine Room 2002 Hatteras 50 Convertible - Tide Up II