



WAF1 CREW

50' (15.24m) 2003 Cranchi
Barrington Rhode Island United States



OVERVIEW

\$350,000

Manufacturer:	Cranchi	Hull Material:	Fiberglass
Engines:	2 Volvo	Cruise Speed:	Knots
Engine Model:	D-12	Max Speed:	Knots
Engine HP:	715	Cabins/Heads:	3 / 2
Beam:	14' 2"	Fuel Type:	Diesel
Max Draft:	3' 5"	Fuel:	515 G (1949.49 L)
Water:	132 G (499.67 L)		



Chris Davis cdavis@denisonyachting.com

401-239-7719

Data Sheet

Category: Express Cruiser
Subcategory: Aft Cabin
Condition: Used
Model Year: 2003
Beam: 14'2" (4.32m)
Max Draft: 3' 5" (1.04m)
Min Draft: 3' 5" (1.04m)
LOA: 50' (15.24m)
Cabins: 3
Heads: 2

Knots
Knots
Fuel Type: Diesel
Hull Material: Fiberglass

Fuel Tank: 515 gal (1949.49 liters)
Fresh Water: 132 gal (499.67 liters)
Holding Tank: 60 gal (227.12 liters)
Imported: No
HIN/IMO: XGUP6006K203
Stock #: B92049

Engines/Generators

Engine 1

Volvo
D-12
Inboard
715HP
533.18KW
Fuel: Diesel
Hours: 1150
Year: 2003
Location: Port

Engine 2

Volvo
D-12
Inboard
715HP
533.18KW
Fuel: Diesel
Hours: 1150
Year: 2003
Location: Starboard

Summary/Description

This 2003 Cranchi Mediterranée 50 has undergone significant updates, specifically in the last 12 months since the owner's purchase her in 2021.

She is currently being stored indoors and can be viewed by appointment. This boat has an excellent layout. Below are a list of her features. Please read the description section for a full list of updates.

Three Stateroom & Two Head Layout

Twin Volvo D-12 Diesel Engines with Approximately 1,150 Hours

Fischer Panda Generator

Bow Thruster

Air Conditioning & Heating

Garmin & Raymarine Electronics

Hydraulic Tender Garage

Much More!

Updates 2021-2023

12-29-2021 Change oil pump and filter

12-29-2021 Replace coolant port and starboard engine

1-28-2022 Straightline fabrication/interior bedding

replacement, exterior helm and cockpit

cushions, replacement of complete canvas

enclosure

1-28-2022 NorEast marine/replace chiller system

2-25-2022 Thru hulls - Replace engine generator

and chiller intake thru-hulls. Forespar

valves. New strainers and supply hoses

Dry fit engine intake valves. Float valve

and stem into epoxy, glue stem with

life-caulk. Antifouling coating. Replace

bonding wires on engine thru-hulls

2-25-2022 Install general zincs exterior

3-31-2022 Sand and paint bottom one coat

3-31-2022 Volvo shift problem

3-31-2022 Thru hulls - replace engine generator

and chiller intake thru-hulls. Forespar valves

cleaned all mounting surfaces. Dry fit

Forespar aft thru-hulls with backing pads

glue stem on the exterior with lifeseal

glue and float backing pads attached to

thru-hulls in place. Install new strainers

and supply hoses. Dry fit engine intake

valves, make backing plates. Float valve

and stem into epoxy, glue stem with

life-caulk. Strip away old paint on the

exterior, prime surface and apply antifouling coating. Replace bonding wires on

engine thru-hulls.

5-27-2022 Install engine zincs

5-27-2022 Change belts main engine

5-27-2022 Repair bilge pump and shower sump

5-27-2022 Repair fresh water leak in water system

5-27-2022 Replace Crankcase and air filters main eng

5-27-2022 Remove broken fitting Stbd Trans cooler

5-27-2022 New docking fenders with covers & lines

6-30-2022 Change fuel filters main engines

6-30-2022 Replace broken trim cylinders/replace

trim pump and four trim cylinders

6-30-2022 HeadSync toilet repair, bow seal, vac pump

6-30-2022 Replace forward hatch

6-30-2022 Compound and wax hull

6-30-2022 Compound and wax cockpit

6-30-2022 Touch up gel-coat starboard side

6-30-2022 Air conditioning ducting – make access

panels for a/c ducting replacement

6-30-2022 Replace additional ducting

7-29-2022 NorEast marine/replace chiller system

8-30-2022 Remove backs of seats onboard, remove

nose cone in engine room and cockpit

seating

8-30-2022 Straightline fabrication/interior bedding

replacement, exterior helm and cockpit

cushions, replacement of complete

canvas enclosure

9-29-2022 Cay electronics

1-31-2023 Change fuel filters x 4

1-31-2023 Install general zincs/exterior and internal

engine

1-31-2023 Replace batteries

1-31-2023 Change engine impeller

1-31-2023 Service thruster

1-31-2023 House bank battery charger

1-31-2023 Charger generator battery

1-31-2023 Battery cables and battery cable ends/

make new battery cable jumpers,

change cable ends

1-31-2023 Generator; remove and rebuild by

Fischer Panda

1-31-2023 Clean air intake filters

1-31-2023 Build crate to ship generator

1-31-2023 Paint bottom 2 coats

1-31-2023 Compound and wax hull

1-31-2023 Hull touch ups

2-27-2023 House bank battery charger

2-27-2023 Charger generator battery

2-27-2023 Compound and wax superstructure

2-27-2023 Hull touch ups

2-27-2023 Remove old sea deck/wood not sealed

properly

2-27-2023 Deck areas sand all surfaces, fill all holes

Disclaimer

The company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change or withdrawal without notice.

