



Never Say Never

33' (10.06m) 1990 Bertram Flybridge Cruiser St. Simons Island Georgia United States

OVERVIEW

Manufacturer: Engines: Engine Model: Engine HP: Beam: Max Draft: Water: Bertram 2 Yanmar 0 12' 6" 3' 0" 90 G (340.69 L)

Hull Material: Cruise Speed: Max Speed: Cabins/Heads: Fuel Type: Fuel:

Fiberglass 24 Knots 31 Knots / Diesel 255 G (965.28 L)



<u>\$</u>66,500



912 506 5674

Corinna Rogers corinna@suncruising.com



Data Sheet

Category: Sport Fishing Subcategory: Flybridge Condition: Used Model Year: 1990 Beam: 12'6'' (3.81m) Max Draft: 3' (0.91m) LOA: 33' (10.06m) LWL: 33' (10.06m) Maximum Speed: 31 Knots Cruise Speed: 24 Knots Fuel Type: Diesel Hull Material: Fiberglass Bridge Clearance: 12' 6 Fuel Tank: 255 gal (965.28 liters) Fresh Water: 90 gal (340.69 liters) Holding Tank: 25 gal (94.64 liters) Imported: No HIN/IMO: BERH0838D990 In Stock: Yes

Engines/Generators

Engine 1

Yanmar Fuel: Diesel Year: 2006 Location: Port

Generator 1

Onan

Engine 2

Yanmar Fuel: Diesel Year: 2006



Summary/Description

This 1990 Bertram Sportfisher with low hours on the repowered Yanmar diesels, brand new generator (under 10h), new Garmin GPS, hardtop flybridge with full enclosure is ready to take offshore.

Highlights

- Repowered Yanmar diesel engines (approx hours 300h)
- Brand new Cummins Onan 9kw generator installed in 2022 (under 10h)
- New GarminGPS map 7612xsv, 12 inch (2022)
- Epirp and liferaft included
- Amtico Teak & Holly Flooring (no carpet)
- New Aluminum outriggers
- Fiberglass Hardtop for flybridge with full canvas enclosure
- Accommodations: 2 cabins (v-berth and bunk beds), separate head/shower, galley with fridge, sink, 3 burner princess stove, plenty of storage
- Boat cruises at around 22 knots with top speed of 28 knots, burning around 15-20 gph.

This model came with several new features that previous years didn't have:

- Separate stall shower
- 1 1/4" all aluminum welded deck rails
- White powder coated grab rails and white resin steps to bridge
- Enclosed rope lockers on both sides of cockpit (previous years had open lockers)
- Light oak interior with built in cabinets on both left and right dash in main cabin

Electronics:

- GarminGPS map 7612xsv, 12 inch
- Garmin 424 XHDS 4' 4kw open array radar
- Garmin Reactor autopilot with brushless smart pump and shadow drive
- (2) Garmin GT50M-TH transducers 500w with Clearvu/Sidevu/Downvu chirp and depth
- Icom 602 with command mic on bridge
- Second command mic inside cabin door
- Icom 502 in cabin

Upgrade/Maintenance history:

2020-2024:

- New Garmin Chartplotter (2022)
- New Isinglass (2022)
- New Onan marine generator (approx. 3h)
- Bottom antifoul paint (2022)



2018/2019 updates:

- New stereo and VHF 2018
- New outriggers 2018
- New wallpaper 2018
- New A/C Unit 2018 (currently not working)
- New helm seats 2018
- Added 2x30 amp power outlets in Cockpit 2018
- Props serviced 2019
- New flatscreen TV's 2019

2016/2017 updates:

- Bridge enclosure installed (Harding Sails)
- OceanAir pleated blinds in Salon updated (Maloney Interiors)
- NOCO Genius 30 amp 3-bank battery charger installed
- New shower box with float and bilge pump installed
- New anchor light
- New wiring for electronics including NMEA interfacing with VHF radio
- New Nautley Dinghy ramp HD+ installed on swim platform
- New Sea Star 2.4 helm with new hydraulic lines installed
- New electric head with macerator and replaced seals and tank gauge on holding tank
- New Fireboy system including wiring to bridge emergency shutoff
- (2) New Fireboy Xintex carbon monoxide detectors installed

2006 - 2008 updates:

- New Yanmars 6LYA-STP 370hp
- New Cruz Pro Fuel gauge installed
- New custom 6" side exhaust ports added
- All new engine room vent hoses and blower hoses installed
- All new system hoses installed for AC, Water, Bilge Pumps, Head, etc.
- All new bronze sea strainers installed
- All new Groco full-flow thru-hull ball valves installed
- All new bilge pump thru hull fittings replaced
- All new thru hull vent fittings replaced for head, water tank and fuel tank
- All hull side air vents replaced and color matched to hull
- New crash pump valves installed in-line with water intakes
- Two new garboard hull drain plugs installed
- New 25 gallon holding tank
- New SMX Digital AC/Heat pump control
- Entire bilge awlgripped white
- New battery boxes
- New 90 gallon water tank



- New Reverso Oil change system for 2 engines, 2 transmissions, and generator
- New engine room steps
- All aluminum wire clamps throughout all bilges have been replaced with stainless steel clamps
- 4 new engine room lights installed to supplement existing single light
- 2 new water tank compartment lights installed
- Two additional high capacity bilge pumps installed
- Additional 110 outlets installed in cabin
- New mini-blinds installed in cabin
- Bennett Trim Tab indicators installed
- New Amtico Teak & Holly Flooring installed in entire cabin in Fall of 2008
- Boat wired for dockside cable
- Custom thru-the-transom hawse plates added for dock lines to go thru transom
- New 15" Flat Screen TV with DVD installed in V-berth
- New 17" Flat Screen TV installed in Salon
- New Stainless life-ring cockpit mount

2004 - 2005 updates:

- Hard fiberglass top (aluminum frame) with full strataglass enclosure and bridge lighting
- All new bridge cushions, helm cushions and cockpit coming
- New Textaline black windshield cover
- New V-Berth and Twin Bunk cushions and new covers
- Swim Platform was re-awlgripped and new stainless support stanchions installed along with undermount, white rubber coated, stainless steel swim ladder
- Rear cockpit was recored and awlgripped
- Custom helm console was reconfigured for all new electronics and awlgripped
- Windscreen frame and all grab rails were re-powdercoated
- New tinted windscreens installed
- Black and Gold boot stripes on 3 sides of bridge as well as dual stripes from bow to rear cabin sides re-awlgripped
- Cockpit lights replaced, shorepower receptacles upgraded to stainless from plastic and new freshwater spigot replaced
- New bridge cockpit lights
- New matching 8' VHF antenna and 8' AM/FM antenna on new stainless mounts
- New freshwater system circulating pump
- New oak towel racks in bathroom
- Three new bilge pumps
- New bathroom blower
- New Generator compartment blower
- New Galley sink and Head faucets installed
- New U-Line Refrigerator installed
- New Shower sump pump with basin
- New Fortress anchor
- New "Bertram 33" Stainless Steel Insignias installed on both sides of cabin

Additional comments:

Waterheater was removed and A/C is currently not working.





































































































































































































