



The Green Squirrel

41' (12.50m) 2010 Sea Ray 390 Sedan Bridge
Aventura Florida United States



OVERVIEW

\$199,000

Manufacturer:	Sea Ray	Hull Material:	Fiberglass
Engines:	2 MerCruiser	Cruise Speed:	18 Knots
Engine Model:		Max Speed:	25 Knots
Engine HP:	370	Cabins/Heads:	1 / 1
Beam:	13' 0"	Fuel Type:	Gas/Petrol
Max Draft:	"	Fuel:	300 G (1135.62 L)
Water:	75 G (283.91 L)		





Data Sheet

Category: Motor Yachts
Condition: Used
Model Year: 2010
Beam: 13' (3.96m)
LOA: 40' 7" (12.37m)
Cabins: 1
Heads: 1

Maximum Speed: 25 Knots
Cruise Speed: 18 Knots
Fuel Type: Gas/Petrol
Hull Material: Fiberglass

Fuel Tank: 300 gal (1135.62 liters)
Fresh Water: 75 gal (283.91 liters)
Holding Tank: 35 gal (132.49 liters)

Engines/Generators

Engine 1

MerCruiser
Inboard
370HP
275.91KW
Fuel: Gas/Petrol
Hours: 460

Engine 2

MerCruiser
Inboard
370HP
275.91KW
Fuel: Gas/Petrol
Hours: 460

Summary/Description

390 Sedan Bridge

2010 Sea Ray 390 Sedan Bridge

Description

2010 Sea Ray 390 Sedan Bridge Priced to Sell!!!

Everything about this beauty is designed with extended voyages in mind, including its outstanding ride and sea-keeping abilities, open and airy cabin, and two well-appointed staterooms. While the captain takes command at the helm, guests will enjoy breathtaking views from the generous bridge seating. In comfort as well as style, the 390 Sedan Bridge will transport you to distant harbors and back again.

- spot light bulb and gear replacement
- compass for autopilot replaced
- bottom paint last year
- running gear and props reconditioned
- trim tabs replaced and new hardware installed
- new agm batteries 2023 and
- new battery charger 2023
- bottom zincs regularly maintained and replaced 2 weeks ago.
- bow thruster controller replaced

Engines

- Port and starboard water pumps replaced
- port and starboard fuel coolers rebuilt, pressure checked and port fuel cooler high and low pumps replaced.
- oils changed at 393
- new manifolds
- new riser turbulator gaskets
- injectors pulled, checked and cleaned
- new spark plugs



- flame arrestor cleaned

Only 460 Hours

Disclaimer

The company offers the details of this vessel in good faith but cannot guarantee or warrant the accuracy of this information nor warrant the condition of the vessel. A buyer should instruct his agents, or his surveyors, to investigate such details as the buyer desires validated. This vessel is offered subject to prior sale, price change or withdrawal without notice.



























